

Mahindra First Choice Wheels Certification Report



2019 HYUNDAI VENUE(2019-2020) SX 1.4 (O) CRDI

East Champaran | 32644 km | Diesel | Manual | Blue Colour | 1st Owner

✓ Eligible for Warranty ✓ 140+ Points Inspected

Overall
Fair Buy 🍏

Exterior Fair



Interior Fair



Engine & Transmission Fair



M R Mahajan
M Mahajan
Head Certification
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

Vehicle Details

Owner Name

Sonakshi Automobiles

Registration Month

July

Registration Year

2019

Color

Blue

Odometer Reading(km)

32644

Registration Number

BR07XXXXXX

No of Owners

1

Insurance Status

Not available

Chassis Number

MALFXXXXXXXXXXXXX

Engine Number

D4FCXXXXXXXXX

Remarks

.

Remarks

.

RC Status

RC Available

PUC Certificate

Available

Keys Availability

In Good Condition

Transfer Papers Availability

**All RTO papers available
and valid NOC from Bank**

Vehicle Status

Certified

[View in Website](#)

Front Bumper

Condition : Excellent

No damage

Grill / Emblem

Condition : Excellent

No scratch & in good condition

Windscreen glass

Condition : Excellent

Clean, No marks

Right Running Board

Condition : Excellent

No dents & scratches

Right Quarter Panel

Condition : Excellent

No dents or scratches

Right Fender

Condition : Excellent

No dents or scratches

Front Right Door

Condition : Excellent

No dents or scratches

Rear Right Indicator

Condition : Excellent

Working & in good condition

Rear Right Indicator

Condition : Excellent

Working & in good condition

Right Doors Functionality

Condition : Excellent

Smooth to operate

RH Side All Pillars

Condition : Excellent

Spot welding original

Right Side View Mirror

Condition : Excellent

Operating smoothly & no scratches

Windscreen Washer and Jets

Condition : Excellent

Smooth operations

Trunk

Condition : Excellent

No dents or scratches

Bonnet

Condition : Excellent

No dents or scratches

Front Right Tyre

Condition : Excellent

Same Make/ Good & > 80% life

Rear Right Tyre

Condition : Excellent

Same Make/ Good & > 80% life

Trunk, Bonnet and Hood functionality

Condition : Excellent

Operating smoothly

Exterior (Continued...)

Rear Bumper

Condition : **Excellent**

No damage

Spare Tyre

Condition : **Excellent**

Same Make/ Good & > 80% life

Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

Left Running Board

Condition : **Excellent**

No dents or scratches

Left Quarter Panel

Condition : **Excellent**

No dents or scratches

Left Fender

Condition : **Excellent**

No dents or scratches

Front Left Door

Condition : **Excellent**

No dents or scratches

Rear Left Door

Condition : **Excellent**

No dents or scratches

Left Doors Functionality

Condition : **Excellent**

Smooth to operate

LH Side All Pillars

Condition : **Excellent**

Spot welding original

Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

Front Left Tyre

Condition : **Excellent**

Same Make/ Good & > 80% life

Rear Left Tyre

Condition : **Excellent**

Same Make/ Good & > 80% life

Frame or Underbody

Condition : **Excellent**

No panel changed

Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible difference in color of panels

Parking lights Front & Rear

Condition : **Excellent**

Working & in good condition

Right Taillight

Condition : **Excellent**

Working & in good condition

Exterior (Continued...)

Left Taillight

Condition : **Excellent**

Working & in good condition

Rear Left Indicator

Condition : **Excellent**

Working & in good condition

Front Left Indicator

Condition : **Excellent**

Working & in good condition

Front Right Indicator

Condition : **Excellent**

Working & in good condition

Left Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

Right Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

Wheel Rim (Steel / Alloy) (Including Spare Wheel)

Condition : **Excellent**

Good condition

Spare Wheel Cover

Condition : **Excellent**

Good condition

Fog lamps

Condition : **Excellent**

Operating & in good condition

Alloy Wheels

Condition : **Excellent**

Good condition

Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

Carpet - Cleanliness, torn off, proper size

Condition : Excellent

OK & almost negligible stains

All Door Trim

Condition : Excellent

Clean & no rattling noise

Seat Adjustment

Condition : Excellent

Working smoothly

Safety Belts Inertia Locking System

Condition : Excellent

Smooth to operate

Dashboard

Condition : Excellent

Clean & no rattling noise

Rubber Beading (All)

Condition : Excellent

Clean & No wear & tear marks

Window Mechanisms

Condition : Excellent

Operating smoothly (All 4)

Inside Rear View Mirror

Condition : Excellent

Operating smoothly & no scratches

Seat Condition

Condition : Excellent

Seat cover is in good condition

Instrument Panel Gauges

Condition : Excellent

Operations & Visibility good

Instrument Panel Warning Lights

Condition : Excellent

Operating

Horns

Condition : Excellent

Operating

Wipers (all speeds)

Condition : Excellent

Smooth to operate

Combination Switch

Condition : Excellent

Operating smoothly & not faded

Clock / Stereo controls / Power windows & other electrical controls

Condition : Excellent

Working smoothly

Cigarette Lighter / Charger / USB Port

Condition : Excellent

Working & in good condition

Interior lights

Condition : Excellent

Working smoothly

Hazard lights

Condition : Excellent

Working & in good condition

Interior (Continued...)

Trunk Light

Condition : **Excellent**

Working & in good condition

AC Cooling

Condition : **Excellent**

Excellent (Climate control - 4.5 to 6.50) / (Normal 7.5 to 9.5)

Heating

Condition : **Excellent**

Working

Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

Manual / Power Steering (Electronic/Hydraulic)

Condition : **Excellent**

Operations are smooth & no noise/ play observed

Hand Brake

Condition : **Excellent**

Smooth operations

Music System

Condition : **Excellent**

Working properly & in very good condition

Speakers

Condition : **Excellent**

Proper cover & output in good condition (sound quality)

Defogger

Condition : **Excellent**

Operating & in good condition

CNG/LPG kit

Condition : **NA**

Not Applicable

Central Locking System

Condition : **Excellent**

In good condition & smooth operation

Jack And Tommy (Tool Kit)

Condition : **Good**

Available & in good condition

Dickey Shock Absorber

Condition : **Excellent**

Ok & in good condition

**Battery - Specification /
Voltage check / Check
Petroleum Jelly Application**

Condition : **Good**

Operating & > 3 years old

Alternator

Condition : **Excellent**

Smooth Operations

Starter Motor

Condition : **Excellent**

Smooth Operations

Fuel Pump (Petrol)

Condition : **Excellent**

Smooth operations

AC Compressor

Condition : **Excellent**

Working smoothly

Condenser Fan

Condition : **Excellent**

No noise & smooth operation
(Proper cut-off)

Blower motor

Condition : **Excellent**

Smooth operations

Steering Rattling Noise

Condition : **Excellent**

Smooth & no noise

Suspension Arms

Condition : **Excellent**

Working smoothly

Front struts (Shock absorber)

Condition : **Excellent**

No noise, Smooth Operation

Rear Shock Absorber/Spring

Condition : **Excellent**

No noise & smooth Operation

Stabiliser Bar & Other Bushes

Condition : **Excellent**

No noise & smooth operation

ABS

Condition : **Excellent**

Smooth Operation (High Speed
Pedal Vibration)

Brake Pedal

Condition : **Excellent**

Smooth Operation & Play

Check Front Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

Check Rear Brake

Condition : **Excellent**

Smooth operation & braking
efficiency

**Master Cylinder / Wheel
Cylinder**

Condition : **Excellent**

Smooth operation

Engine & Transmission (Continued...)

Braking Efficiency

Condition : **Excellent**

Operating smoothly

Gearshift level (Gear Engagement)

Condition : **Excellent**

Smooth operation

Gear Lever Play

Condition : **Excellent**

Smooth operation

Clutch Engagement

Condition : **Excellent**

Smooth operation

Clutch Pedal / Cable Operation

Condition : **Excellent**

Smooth

Axle Noise/Drive Shaft Boot Damage

Condition : **Excellent**

No noise

Front & Rear Wheel Bearings

Condition : **Excellent**

No noise

Differential

Condition : **Excellent**

Smooth operations

Alignment/Balancing

Condition : **Excellent**

No pulling

Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

No Leakage/ Good condition
(Changed during
Refurbishment)

Engine and Transmission Mountings

Condition : **Excellent**

No Noise/Vibrations

Abnormal Engine Noise/ Back Compression

Condition : **Excellent**

No noise (Tappet as well as
Knocking noise)

Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**

No leakage/ Good condition
(Changed during
refurbishment)

Gasket: Tappet Cover

Condition : **Excellent**

No leakage

Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**

No leakage

Engine Oil Leaks: Sump Gasket

Condition : **Excellent**

No leakage

Engine Oil Leaks: Sump Damage

Condition : **Excellent**

No leakage/ Damage

Exhaust system

Condition : **Excellent**

No noise, No rusting sign &
smooth Operation

Engine & Transmission (Continued...)

Smoke Color (Blue)

Condition : **Excellent**

No Color

Smoke Color (Black)

Condition : **Excellent**

No Color

Smoke Color (White)

Condition : **Excellent**

No Color

Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

Hose Pipe

Condition : **Excellent**

Good condition

Alternator Drive Belt

Condition : **Excellent**

Good condition

Water Pump

Condition : **Excellent**

Good Condition & no noise

Tappet Noise

Condition : **Excellent**

No noise

Turbo Charger

Condition : **Excellent**

Good condition

Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

Engine & Transmission (Continued...)

Fuel Tank and Pipes

Condition : **Excellent**

Good condition

Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

Vehicle Images

Front Side



11 Oct 2022 16:20:22

Lat 26.8072447,Long 84.5088753

Front Right Side



11 Oct 2022 16:20:30

Lat 26.8072501,Long 84.5088981

Front Right Tyre



11 Oct 2022 16:20:35

Lat 26.8072029,Long 84.5086407

Right Side



11 Oct 2022 16:20:55

Lat 26.8071366,Long 84.5087085

Rear Right Tyre



11 Oct 2022 16:21:02

Lat 26.8072465,Long 84.5087432

Rear Right Side



11 Oct 2022 16:21:29

Lat 26.8072535,Long 84.5088856

Back Side



11 Oct 2022 16:21:39

Lat 26.8072458,Long 84.5088729

Rear Left Side



11 Oct 2022 16:21:58

Lat 26.8072319,Long 84.5088853

[View this car in Website](#)

Rear Left Tyre



11 Oct 2022 16:22:07

Lat 26.8072449,Long 84.5088996

Left Side



11 Oct 2022 16:22:15

Lat 26.8072456,Long 84.5088895

Front Left Tyre



11 Oct 2022 16:22:40

Lat 26.8072503,Long 84.5087541

Front Left Side



11 Oct 2022 16:22:29

Lat 26.8072083,Long 84.5085711

Odometer



11 Oct 2022 16:24:36

Lat 26.8072551,Long 84.5088654