

## Mahindra First Choice Wheels Certification Report

**2019 MARUTI SUZUKI ERTIGA(2018-2022) ZXI PLUS BS-VI**

North Delhi | 40811 km | Petrol | Manual | White Colour | 1st Owner

🟢 Eligible for Warranty 🟢 140 Points InspectedExterior FairInterior FairEngine & Transmission Fair

Overall  
**Fair Buy** 🟢



*M R Mahajan*  
M Mahajan  
Head Certification  
& Warranty - MFCWL

[Explore this car in website](#)[View in Website](#)

Overall rating is the 'quality score' of a vehicle derived from a **140+** point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

## Vehicle Details

Owner Name

**Cherish Carmint**

Registration Month

**April**

Registration Year

**2019**

Color

**White**

Odometer Reading

**40811**

Registration Number

**DL2CXXXXXX**

No of Owners

**1**

Insurance Status

**Not available**

Chassis Number

**MA3BXXXXXXXXXXXXX**

Engine Number

**K15BXXXXXXXXX**

Remarks

**Service due,**

Remarks

**Service due,**

RC Status

**RC Available**

PUC Certificate

**Not Available**

Keys

**In Good Condition**

Transfer Papers Availability

**All Papers available**

Vehicle Status

**Certified**

[View in Website](#)

**Front Bumper**

Condition : Good

Clean & slight color difference

**Grill / Emblem**

Condition : Excellent

No scratch & in good condition

**Windscreen glass**

Condition : Excellent

Clean, No marks

**Right Running Board**

Condition : Excellent

No dents & scratches

**Right Quarter Panel**

Condition : Good

1-2 minor dents & minimal scratches

**Right Fender**

Condition : Excellent

No dents or scratches

**Front Right Door**

Condition : Excellent

No dents or scratches

**Rear Right Indicator**

Condition : Excellent

Working & in good condition

**Rear Right Indicator**

Condition : Excellent

Working & in good condition

**Right Doors Functionality**

Condition : Excellent

Smooth to operate

**RH Side All Pillars**

Condition : Excellent

Spot welding original

**Right Side View Mirror**

Condition : Excellent

Operating smoothly & no scratches

**Windscreen Washer and Jets**

Condition : Excellent

Smooth operations

**Trunk**

Condition : Excellent

No dents or scratches

**Bonnet**

Condition : Excellent

No dents or scratches

**Front Right Tyre**

Condition : Satisfactory

Same Make/ Good & > 40% life

**Rear Right Tyre**

Condition : Satisfactory

Same Make/ Good & > 40% life

**Trunk, Bonnet and Hood functionality**

Condition : Excellent

Operating smoothly

## Exterior (Continued...)

### Rear Bumper

Condition : **Good**

Clean & slight color difference

### Spare Tyre

Condition : **Good**

Same Make/ Good & > 60% life

### Number Plate (Front & Rear)

Condition : **Excellent**

Good condition

### Left Running Board

Condition : **Satisfactory**

2-3 minor dents & minor scratches

### Left Quarter Panel

Condition : **Excellent**

No dents or scratches

### Left Fender

Condition : **Excellent**

No dents or scratches

### Front Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

### Rear Left Door

Condition : **Good**

1-2 minor dents & minimal scratches

### Left Doors Functionality

Condition : **Good**

Smooth to operate but little hinge play & no noise

### LH Side All Pillars

Condition : **Excellent**

Spot welding original

### Left Side View Mirror

Condition : **Excellent**

Operating smoothly & no scratches

### Fuel Cap - Check Operation/ Noise

Condition : **Excellent**

Operating smoothly

### Front Left Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

### Rear Left Tyre

Condition : **Satisfactory**

Same Make/ Good & > 40% life

### Frame or Underbody

Condition : **Good**

1-2 panels changed

### Paint, Polishing and Gloss

Condition : **Excellent**

No difference or negligible difference in color of panels

### Parking lights Front & Rear

Condition : **Excellent**

Working & in good condition

### Right Taillight

Condition : **Excellent**

Working & in good condition

## Exterior (Continued...)

### Left Taillight

Condition : **Excellent**

Working & in good condition

### Rear Left Indicator

Condition : **Excellent**

Working & in good condition

### Front Left Indicator

Condition : **Excellent**

Working & in good condition

### Front Right Indicator

Condition : **Excellent**

Working & in good condition

### Left Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

### Right Headlight (Both Points)

Condition : **Excellent**

Working & in good condition

### Wheel Rim (Steel / Alloy) (Including Spare Wheel)

Condition : **Excellent**

Good condition

### Spare Wheel Cover

Condition : **Excellent**

Good condition

### Fog lamps

Condition : **Excellent**

Operating & in good condition

### Alloy Wheels

Condition : **Excellent**

Good condition

### Wheel Cap

Condition : **Excellent**

All 4 available & in good condition

**Carpet - Cleanliness, torn off, proper size**

Condition : Good

Ok but some stains

**All Door Trim**

Condition : Good

Dirty & negligible rattling noise

**Seat Adjustment**

Condition : Excellent

Working smoothly

**Safety Belts Inertia Locking System**

Condition : Excellent

Smooth to operate

**Dashboard**

Condition : Excellent

Clean & no rattling noise

**Rubber Beading (All)**

Condition : Excellent

Clean & No wear & tear marks

**Window Mechanisms**

Condition : Excellent

Operating smoothly (All 4)

**Inside Rear View Mirror**

Condition : Excellent

Operating smoothly & no scratches

**Seat Condition**

Condition : Excellent

Seat cover is in good condition

**Instrument Panel Gauges**

Condition : Excellent

Operations & Visibility good

**Instrument Panel Warning Lights**

Condition : Excellent

Operating

**Horns**

Condition : Excellent

Operating

**Wipers (all speeds)**

Condition : Excellent

Smooth to operate

**Combination Switch**

Condition : Excellent

Operating smoothly & not faded

**Clock / Stereo controls / Power windows & other electrical controls**

Condition : Excellent

Working smoothly

**Cigarette Lighter / Charger / USB Port**

Condition : Excellent

Working & in good condition

**Interior lights**

Condition : Excellent

Working smoothly

**Hazard lights**

Condition : Excellent

Working & in good condition

## Interior (Continued...)

### Trunk Light

Condition : **Excellent**

Working & in good condition

### AC Cooling

Condition : **Good**

Good

### Heating

Condition : **Excellent**

Working

### Air distribution (AC Vents)

Condition : **Excellent**

Operating & in good condition

### Recirculation/ Fresh air

Condition : **Excellent**

Operating Smoothly

### Manual / Power Steering (Electronic/Hydraulic)

Condition : **Excellent**

Operations are smooth & no noise/ play observed

### Hand Brake

Condition : **Excellent**

Smooth operations

### Music System

Condition : **Excellent**

Working properly & in very good condition

### Speakers

Condition : **Excellent**

Proper cover & output in good condition (sound quality)

### Defogger

Condition : **Excellent**

Operating & in good condition

### CNG/LPG kit

Condition : **NA**

Not Applicable

### Central Locking System

Condition : **Excellent**

In good condition & smooth operation

### Jack And Tommy (Tool Kit)

Condition : **Excellent**

Available & in very good condition

**Dickey Shock Absorber**

Condition : **Good**

Ok with No leakage marks /  
Operation slightly weak

**Battery - Specification /  
Voltage check / Check  
Petroleum Jelly Application**

Condition : **Good**

Operating & > 3 years old

**Alternator**

Condition : **Excellent**

Smooth Operations

**Starter Motor**

Condition : **Excellent**

Smooth Operations

**Fuel Pump ( Petrol)**

Condition : **Excellent**

Smooth operations

**AC Compressor**

Condition : **Excellent**

Working smoothly

**Condenser Fan**

Condition : **Excellent**

No noise & smooth operation  
(Proper cut-off)

**Blower motor**

Condition : **Excellent**

Smooth operations

**Steering Rattling Noise**

Condition : **Excellent**

Smooth & no noise

**Suspension Arms**

Condition : **Excellent**

Working smoothly

**Front struts (Shock absorber)**

Condition : **Excellent**

No noise, Smooth Operation

**Rear Shock Absorber/Spring**

Condition : **Excellent**

No noise & smooth Operation

**Stabiliser Bar & Other Bushes**

Condition : **Satisfactory**

Ok but slightly hard

**ABS**

Condition : **Excellent**

Smooth Operation (High Speed  
Pedal Vibration)

**Brake Pedal**

Condition : **Excellent**

Smooth Operation & Play

**Check Front Brake**

Condition : **Excellent**

Smooth operation & braking  
efficiency

**Check Rear Brake**

Condition : **Excellent**

Smooth operation & braking  
efficiency

**Master Cylinder / Wheel  
Cylinder**

Condition : **Excellent**

Smooth operation



## Engine & Transmission (Continued...)

### Braking Efficiency

Condition : **Excellent**

Operating smoothly

### Gearshift level (Gear Engagement)

Condition : **Excellent**

Smooth operation

### Gear Lever Play

Condition : **Excellent**

Smooth operation

### Clutch Engagement

Condition : **Excellent**

Smooth operation

### Clutch Pedal / Cable Operation

Condition : **Excellent**

Smooth

### Axle Noise/Drive Shaft Boot Damage

Condition : **Excellent**

No noise

### Front & Rear Wheel Bearings

Condition : **Excellent**

No noise

### Differential

Condition : **Excellent**

Smooth operations

### Alignment/Balancing

Condition : **Excellent**

No pulling

### Transmission Oil (Manual/ Automatic)

Condition : **Excellent**

No Leakage/ Good condition  
(Changed during  
Refurbishment)

### Engine and Transmission Mountings

Condition : **Excellent**

No Noise/Vibrations

### Abnormal Engine Noise/ Back Compression

Condition : **Excellent**

No noise (Tappet as well as  
Knocking noise)

### Engine Oil Leaks: Cylinder Head Gasket

Condition : **Excellent**

No leakage/ Good condition  
(Changed during  
refurbishment)

### Gasket: Tappet Cover

Condition : **Excellent**

No leakage

### Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

Condition : **Excellent**

No leakage

### Engine Oil Leaks: Sump Gasket

Condition : **Excellent**

No leakage

### Engine Oil Leaks: Sump Damage

Condition : **Excellent**

No leakage/ Damage

### Exhaust system

Condition : **Excellent**

No noise, No rusting sign &  
smooth Operation

## Engine & Transmission (Continued...)

### Smoke Color (Blue)

Condition : **Excellent**

No Color

### Smoke Color (Black)

Condition : **Excellent**

No Color

### Smoke Color (White)

Condition : **Excellent**

No Color

### Air Filter

Condition : **Excellent**

Good condition (Changed during refurbishment)

### Radiator /Condenser

Condition : **Excellent**

Good Condition & no damage/rusting sign

### Engine oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during RF)

### Coolant

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

### Brake Oil

Condition : **Excellent**

No Leakage/ Good condition (Changed during refurbishment)

### Hose Pipe

Condition : **Excellent**

Good condition

### Alternator Drive Belt

Condition : **Excellent**

Good condition

### Water Pump

Condition : **Excellent**

Good Condition & no noise

### Tappet Noise

Condition : **Excellent**

No noise

### Turbo Charger

Condition : **NA**

Not Applicable

### Heater Plugs / Spark Plugs

Condition : **Excellent**

Good condition (Changed during refurbishment)

### Radiator Fan

Condition : **Excellent**

No noise & smooth Operation (Proper cut-off)

### Charcoal Canister

Condition : **Excellent**

No damage & Petrol fume

### Ignition Coil (petrol only)

Condition : **Excellent**

Working smoothly

### Ignition Wire Harness (petrol only)

Condition : **Excellent**

Wiring & insulation good condition

## Engine & Transmission (Continued...)

### Fuel Tank and Pipes

Condition : **Excellent**

Good condition

### Fuel Filter (Petrol & Diesel)

Condition : **Excellent**

Good condition (Changed during refurbishment)

### Fuel Injection Pump (Diesel)

Condition : **Excellent**

No leakage & in good condition

## Vehicle Images

### Front Side



Sep 23, 2022 12:57:48 PM

Lat 28.6904348,Long 77.1521664

### Front Right Side



Sep 23, 2022 12:57:57 PM

Lat 28.6903099,Long 77.1522364

### Front Right Tyre



Sep 23, 2022 12:58:03 PM

Lat 28.6902753,Long 77.1523154

### Right Side



Sep 23, 2022 12:58:09 PM

Lat 28.6902858,Long 77.1523229

### Rear Right Tyre



Sep 23, 2022 12:58:16 PM

Lat 28.6902977,Long 77.1523144

### Rear Right Side



Sep 23, 2022 12:58:22 PM

Lat 28.6903828,Long 77.1522506

### Back Side



Sep 23, 2022 12:58:33 PM

Lat 28.6904669,Long 77.1521535

### Rear Left Side



Sep 23, 2022 12:58:41 PM

Lat 28.6904914,Long 77.1521549

[View this car in Website](#)



Rear Left Tyre



Sep 23, 2022 12:58:49 PM

Lat 28.690386, Long 77.1524345

Left Side



Sep 23, 2022 12:58:56 PM

Lat 28.6903902, Long 77.1524184

Front Left Tyre



Sep 23, 2022 12:59:02 PM

Lat 28.6905442, Long 77.1521793

Front Left Side



Sep 23, 2022 12:59:12 PM

Lat 28.6904345, Long 77.1523441

Odometer



Sep 23, 2022 1:02:14 PM

Lat 28.6903669, Long 77.1525627