## Mahindra First Choice Wheels Certification Report



# 2016 RENAULT KWID(2015-2019) RXT

Thiruvananthapuram | 38919 km | Petrol | Manual | Grey Colour | 1st Owner

🧔 Eligible for Warranty 🛛 🧔 140 Points Inspected



Exterior	Excellent
Interior	Excellent
Engine & Transmission	Excellent





Explore this car in website

View in Website

Overall rating is the 'quality score' of a vehicle derived from a **140**+ point inspection process. This is backed by a machine learning algorithm that considers millions of data points to objectively represent the condition of a vehicle in a standard and reliable way

# Vehicle Details

Owner Name

Good Choice Pre Owned Cars

Registration Number

KL01XXXXXX

Chassis Number

In Good Condition

**G839XXXX** 

Remarks

wf-good

Keys

Registration Month

January

Color

Grey

No of Owners

1

Engine Number

B4AAXXXXXXXXXXX

RC Status

**RC Available** 

Transfer Papers Availability

All RTO papers available and valid NOC from Bank

Registration Year

2017

Odometer Reading

38919

Insurance Status

Available

Remarks

wf-good

PUC Certificate

Available

Vehicle Status

Certified

View in Website

## **Exterior Rating - Excellent**

**Front Bumper Condition : Excellent** No damage

Grill / Emblem Condition : Excellent No scratch & in good condition

**Right Quarter Panel** Condition : Excellent No dents or scratches

**Rear Right Indicator** Condition : Excellent

> **RH Side All Pillars** Condition : Excellent Spot welding original

Windscreen Washer and Jets **Condition : Excellent** Smooth operations

Condition : Good 1-2 minor dents & minimal scratches

Trunk

**Front Right Tyre Condition : Satisfactory** Same Make/ Good & > 40% life **Rear Right Tyre Condition : Satisfactory** Same Make/ Good & > 40% life **Right Fender** Condition : Excellent No dents or scratches

Windscreen glass

Clean, No marks

Condition : Excellent

**Rear Right Indicator** Condition : Excellent Working & in good condition

**Right Side View Mirror** Condition : Excellent Operating smoothly & no scratches

Bonnet Condition : Good 1-2 minor dents & minimal scratches

Trunk, Bonnet and Hood functionality

**Condition : Excellent** 

Operating smoothly

# Working & in good condition

**Right Running Board** 

Condition : Excellent

No dents & scratches

**Front Right Door** 

**Condition : Excellent** 

No dents or scratches

**Right Doors Functionality** 

**Condition : Excellent** 

Smooth to operate

O 47 Good

**Rear Bumper** Condition : Excellent No damage

Left Running Board

1-2 minor dents & minimal

1-2 minor dents & minimal

Condition : Good

**Front Left Door** 

Condition : Good

LH Side All Pillars

**Front Left Tyre** 

**Condition : Excellent** 

Spot welding original

**Condition : Satisfactory** 

scratches

scratches

Spare Tyre **Condition : Satisfactory** Same Make/ Good & > 40% life

Left Quarter Panel Condition : Good 1-2 minor dents & minimal scratches

**Rear Left Door** Condition : Good 1-2 minor dents & minimal scratches

Left Side View Mirror **Condition : Excellent** Operating smoothly & no scratches

**Rear Left Tyre Condition : Satisfactory** Same Make/ Good & > 40% life Frame or Underbody Condition : Excellent No panel changed

**Paint, Polishing and Gloss** 

Same Make/ Good & > 40% life

**Condition : Excellent** No difference or negligible difference in color of panels

View this car in Website

**Parking lights Front & Rear Condition : Excellent** Working & in good condition **Right Taillight Condition : Excellent** Working & in good condition

Left Doors Functionality

1-2 minor dents & minimal

Number Plate (Front & Rear)

Condition : Excellent

Good condition

Left Fender

scratches

Condition : Good

Smooth to operate but little hinge play & no noise

Fuel Cap - Check Operation/ Noise **Condition : Excellent** Operating smoothly

Condition : Good

Left Taillight Condition : Excellent Working & in good condition Rear Left Indicator Condition : Excellent Working & in good condition Front Left Indicator Condition : Excellent Working & in good condition

**Right Headlight (Both Points)** 

Working & with very minimal

# **Front Right Indicator**

**Condition : Good** Working & with very minimal scratches Left Headlight (Both Points) Condition : Excellent Working & in good condition

Wheel Rim (Steel / Alloy) (Including Spare Wheel)

Condition : Good

Ok but very little color fading

Alloy Wheels Condition : NA Not Applicable Condition : Excellent Good condition

Spare Wheel Cover

Wheel Cap Condition : Excellent All 4 available & in good condition Fog lamps Condition : Good Operating but lens ok/ Minor

Scratches

Condition : Good

scratches

## **Interior Rating - Excellent**

**Condition : Excellent** 

**Condition : Excellent** 

Smooth to operate

Window Mechanisms

Operating smoothly (All 4)

**Instrument Panel Gauges** 

**Operations & Visibility good** 

**Condition : Excellent** 

Condition : Excellent

proper size

System

Carpet - Cleanliness, torn off,

OK & almost negligible stains

Safety Belts Inertia Locking

All Door Trim Condition : Good Dirty & negligible rattling noise

Dashboard Condition : Good Some scratches & minimal rattling noise

Inside Rear View Mirror Condition : Excellent Operating smoothly & no scratches

> Instrument Panel Warning Lights Condition : Excellent Operating

Wipers (all speeds) Condition : Excellent Smooth to operate

**Condition : Good** Operating but minimal wear & tear marks

**Combination Switch** 

Cigarette Lighter / Charger / USB Port Condition : Excellent Working & in good condition Interior lights Condition : Excellent Working smoothly Seat Adjustment Condition : Excellent Working smoothly

Rubber Beading (All) Condition : Good No cut marks; Wear & tear marks in some places

Seat Condition Condition : Excellent Seat cover is in good condition

Horns Condition : Excellent Operating

Clock / Stereo controls / Power windows & other electrical controls

Condition : Excellent

Working smoothly

Hazard lights Condition : Excellent Working & in good condition Trunk Light Condition : Excellent Working & in good condition

Air distribution (AC Vents) Condition : Excellent Operating & in good condition AC Cooling

**Condition : Excellent** 

Excellent (Climate control - 4.5 to 6.50) / (Normal 7.5 to 9.5)

Recirculation/ Fresh air Condition : Excellent Operating Smoothly

Hand Brake Condition : Good Operating but not very smooth

Defogger

Condition : NA

Not Applicable

Music System Condition : Excellent Working properly & in very good condition

CNG/LPG kit Condition : NA Not Applicable Heating Condition : Excellent Working

# Manual / Power Steering (Electronic/Hydraulic)

Condition : Excellent

Operations are smooth & no noise/ play observed

**Speakers Condition : Good** Ok but sound quality ok

Central Locking System Condition : Excellent In good condition & smooth

operation

Jack And Tommy (Tool Kit) Condition : Good Available & in good condition

View this car in Website

**Dickey Shock Absorber** 

Condition : Good

Ok with No leakage marks / Operation slightly weak

**Starter Motor** Condition : Excellent **Smooth Operations** 

## Battery - Specification / Voltage check / Check **Petroleum Jelly Application**

Condition : Excellent

Operating smooth & < 2 years old

Fuel Pump (Petrol) Condition : Excellent Smooth operations

**Blower motor** 

Condition : Excellent

Smooth operations

**Condenser Fan** Condition : Excellent No noise & smooth operation

**Suspension Arms Condition : Excellent** Working smoothly

Front struts (Shock absorber) Condition : Good Ok but slightly hard & no

**Stabiliser Bar & Other Bushes Condition : Satisfactory** Ok but slightly hard

**Condition : Excellent** Smooth Operation (High Speed Pedal Vibration)

**Check Front Brake** 

Condition : Excellent

Smooth operation & braking efficiency

**Check Rear Brake** Condition : Excellent Smooth operation & braking efficiency

Alternator Condition : Excellent **Smooth Operations** 

**AC Compressor** Condition : Excellent Working smoothly

**Steering Rattling Noise** Condition : Excellent Smooth & no noise

**Rear Shock Absorber/Spring** Condition : Excellent No noise & smooth Operation

**Brake Pedal** Condition : Good Ok but slightly less efficient operations/ No excessive play

Master Cylinder / Wheel Cylinder **Condition : Excellent** 

Smooth operation

(Proper cut-off)

leakage sign

ABS

Braking Efficiency Condition : Excellent Operating smoothly

# Gearshift level (Gear Engagement)

Condition : Excellent

Smooth operation

Clutch Engagement Condition : Excellent Smooth operation Clutch Pedal / Cable Operation Condition : Excellent Smooth

Front & Rear Wheel Bearings Condition : Excellent No noise

# Transmission Oil (Manual/ Automatic)

**Condition : Excellent** 

No Leakage/ Good condition (Changed during Refurbishment)

# Engine Oil Leaks: Cylinder Head Gasket

**Condition : Excellent** 

No leakage/ Good condition (Changed during refurbishment)

# Engine Oil Leaks: Sump Gasket

**Condition : Excellent** No leakage Differential Condition : Excellent Smooth operations

Engine and Transmission Mountings Condition : Excellent No Noise/Vibrations

Gasket: Tappet Cover Condition : Excellent No leakage

Engine Oil Leaks: Sump Damage Condition : Excellent No leakage/ Damage Gear Lever Play Condition : Excellent Smooth operation

Axle Noise/Drive Shaft Boot Damage Condition : Excellent No noise

Alignment/Balancing Condition : Excellent No pulling

## Abnormal Engine Noise/ Back Compression

**Condition : Excellent** 

No noise (Tappet as well as Knocking noise)

# Engine Oil Leaks: Crankcase Oil Seals/ Camshaft

**Condition : Excellent** 

No leakage

# Exhaust system

Condition : Excellent

No noise, No rusting sign & smooth Operation

Smoke Color (Blue)

Condition : Excellent

**Condition : Excellent** 

Good condition (Changed

during refurbishment)

No Color

**Air Filter** 

# Smoke Color (Black) Condition : Excellent No Color

Radiator /Condenser Condition : Excellent Good Condition & no

damage/rusting sign

Condition : Excellent

(Changed during

refurbishment)

**Brake Oil** 

Coolant Condition : Excellent

No Leakage/ Good condition (Changed during refurbishment)

Alternator Drive Belt Condition : Excellent Good condition Water Pump Condition : Excellent Good Condition & no noise

No Leakage/ Good condition

Turbo Charger Condition : NA Not Applicable Heater Plugs / Spark Plugs Condition : Excellent Good condition (Changed during refurbishment)

Charcoal Canister Condition : Excellent No damage & Petrol fume Ignition Coil (petrol only) Condition : Excellent Working smoothly Smoke Color (White) Condition : Excellent No Color

Engine oil

Condition : Excellent

No Leakage/ Good condition (Changed during RF)

Hose Pipe Condition : Excellent Good condition

Tappet Noise Condition : Excellent No noise

Radiator Fan Condition : Excellent No noise & smooth Operation (Proper cut-off)

Ignition Wire Harness (petrol only)

Condition : Excellent

Wiring & insulation good condition

# **Fuel Tank and Pipes**

Condition : Excellent

Good condition

# Fuel Filter (Petrol & Diesel)

Condition : Excellent

Good condition (Changed during refurbishment)

Fuel Injection Pump (Diesel) Condition : Excellent No leakage & in good condition

## Vehicle Images

## Front Side



Mar 22, 2022 3:37:25 PM

Lat 8.6193917,Long 76.9396926

# Front Right Tyre



Mar 22, 2022 3:37:46 PM

Lat 8.6193917,Long 76.9396931

Rear Right Tyre



Mar 22, 2022 3:38:03 PM

Lat 8.6193914,Long 76.9396933

## Back Side



Mar 22, 2022 3:38:15 PM

View this car in Website

Lat 8.6193912,Long 76.9396933

## Front Right Side



Mar 22, 2022 3:37:40 PM

Lat 8.6193915,Long 76.9396931

**Right Side** 



Mar 22, 2022 3:37:59 PM

Lat 8.6193913,Long 76.9396932

## **Rear Right Side**



Mar 22, 2022 3:38:11 PM

Lat 8.6193915,Long 76.9396928





Mar 22, 2022 3:38:21 PM

### Rear Left Tyre



Mar 22, 2022 3:38:26 PM

Lat 8.6193912,Long 76.9396933

## Front Left Tyre



Mar 22, 2022 3:38:47 PM

Lat 8.6193917,Long 76.9396929

## Odometer



Mar 22, 2022 3:39:50 PM

Lat 8.6193912,Long 76.9396933

### Left Side



Mar 22, 2022 3:38:32 PM

Lat 8.6193913,Long 76.9396933

#### Front Left Side



Mar 22, 2022 3:38:56 PM

Lat 8.6193914,Long 76.9396933