


2012 HYUNDAI EON D LITE PLUS

MOHALI

Autoinspekt Rating 6



Color



OTHERS

Transmission



Manual

Odometer



47930 KM

Fuel



Petrol

V-DE-DUPE +ve

VALUATION PRICE ₹
1,19,000

Vehicle Rating And Pricing

Vehicle Details

	Registration Number Vehicle Type	PB10DQ6472 Private
	Manufacturing Month / Year Registration Month / Year	Jan 2012 Feb 2012
	Vehicle Ownership RC Status	1 Owner, NA NO
	Insurance HPA Status , HPA Bank	NA Yes, MMFSL
	Chassis Number Engine Number	MALA151ALCM044185 G3HABM039284

No Damage Reported

Repo

Report Request By
**Mahindra & Mahindra
Financial Services Ltd**

Overall Remarks
 NO DAMAGE VEHICLE

Rating	Vehicle Condition	Engine Condition
10 or 9	Excellent	Excellent
8 or 7	Good	Good
6 or 5	Average	Average
4 or 3	Bad	Bad
2 or 1	Scrap	No Engine

Vehicle Summary :
Average



Approved by
G. Praveen Kumar
G.Praveen Kumar,
Head e-Business.
www.autoinspekt.com



Use your smart phone to scan the QR code and get detailed autoinspekt report



EXTERIORS



FRONT - BONNET	Average	6/10
BUMPER FRONT	Average	6/10
HEAD LAMPS	Average	6/10
RH SIDE - FENDER,DOORS	Average	6/10
REAR	Average	6/10
BUMPER REAR - BONNET	Average	6/10
TAIL LAMPS	Average	6/10
LH SIDE - FENDER , DOORS	Average	6/10
WINDSHIELD & GLASS (ORIGINAL)	Average	6/10
PAINT (ORIGINAL)	Average	6/10
NUMBER OF TYRES		4 TYRES
REMAINING AVERAGE TYRE LIFE		50%
SUNROOF / MOONROOF		NA



INTERIORS



STEERING	Average	6/10
DASHBOARD	Average	6/10
INTERIOR TRIMS	Average	6/10
SEATS		5 Seats
SEATS CONDITION	Average	6/10
SEAT UPHOLSTERY		NA
ACCESSORIES (AUDIO,COVERS)	Average	6/10

ABS	No
Airbags	No
ESP	No

Reverse Parking Assist	No
Alloy wheels	No
Cruise Control	No



SYSTEMS & FUNCTIONS



BATTERY	Bad
STARTER MOTOR	Bad
ALTERNATOR	Bad
CUBIC CAPACITY (CC)	0 cc

ENGINE		
CONDITION		Average
TRANSMISSION		
CONDITION		Good
HVAC		
AC BLOWER	Average	6/10
COOLING	Average	6/10
HEATER	Average	6/10
CHASSIS AND VEHICLE FRAME	Average	6/10
BRAKES	Average	6/10
SUSPENSION	Average	6/10
LPG / CNG Available?		NA
LPG / CNG Endorsed in RC?		NA
ELECTRICAL COMPONENTS		
IGNITION & FUEL SYSTEM	Average	6/10
HEAD LAMP, TAIL LAMP	Good	
POWER WINDOWS	NA	
MUSIC SYSTEM	Average	6/10



VEHICLE CONDITION & DOCUMENT DETAILS



Vehicle Condition	Running	Parking Location	Yard
Insurance Type	NA	RC Status	NO
Repo Date	26/11/2016		

ESTIMATED ASSESSMENT

BUYER MARGIN	15000	WARRANTY COST	5000	REFURB COST	10000
TRANSPORTATION COST	1000	INSURANCE COST	6000	PARKING CHARGES	64080
RTO EXPENSES	15000	TAXES	26000	TOTAL COST	78000



DISCLAIMER

- This report is generated by Autoinspekt - A division of Mahindra First Choice Wheels Ltd (MFCW) at the sole request of the party whom this report is addressed and is to be used solely by the said party for the stated purpose only. Autoinspekt will not be held liable for any loss or liability sustained by any third party relying on the Valuation Report. Autoinspekt has relied on the odometer reading at the time of inspection / valuation and is not responsible for verifying the genuineness thereof.
- As there is no standard price list for pre-owned / used vehicles, the vehicle valuation indicated in the report is our opinion on the market value of the vehicle at the time of our inspection / valuation, based on our standard valuation methodology and procedures. Actual realization may differ from the valuation indicated in the report and Autoinspekt (including its directors and employees) will not be held liable for any direct, indirect, consequential or exemplary damages for any loss resulting from use of this report. Autoinspekt is not responsible for verifying the genuineness of the title documents of the vehicle and its professional opinion on valuation of the car is primarily based on the condition of the vehicle at the time of inspection / valuation.

PHYSICAL VERIFICATION OF REPOSSESSED VEHICLE

Branch	PKT	Verification date	31/01/2017
Stockyard name	JALANDHAR BRANCH	Repossessed since	26/11/2016
Repo Release Date	NA	Stock Current Status	NA

Contract Details

Contract No	3834007	Hirer name	NA
-------------	---------	------------	----

Vehicle Details

Make	HYUNDAI	Year of Mfg	2012
Model	EON	Colour	OTHERS
Whether Registered (Yes/No)	Yes	If Yes, Regn No.	PB10DQ6472
Insurance Status	NA		

Vehicle Condition

Total KM Run	47930	Tyre Condition (Good/Average/Bad)	Bad
Whether the vehicle is in Running Condition (Yes/No)	Yes	Whether the vehicle met with an accident (Yes/No)	No
If Yes, the extent of Damage Occured (Total Damage/Partial Damage)	No Damage		
Condition of the interiors including the seats (Good/Average/Bad)	NA		
Battery, whether Running	No	Vehicle Key	NA
Spare tyre	NA	Air Conditioner	NA
Music System	Yes	Tool box	NA
Others (Please specify)	Average		
Expected Market Price of the vehicle as on date of verification (in RS.) - Verification Price	₹ 119000		



Approved by

 G.Praveen Kumar,
 Head e-Business.
 www.autoinspekt.com

Signature of the Verifier

Signature of (BIC /BA)