



2013 MARUTI SUZUKI SWIFT VDI

CHENNAI

Autoinspekt Rating 5



Color



OTHERS

Transmission



Manual

Odometer



NA

Fuel



Diesel

V-DE-DUPE +ve

VALUATION PRICE ₹
1,53,400

Vehicle Rating And Pricing

Vehicle Details



Registration Number **TN12B0576**
Vehicle Type **Taxi**




Manufacturing Month / Year **Feb 2013**
Registration Month / Year **Mar 2013**



Vehicle Ownership **1 Owner, swift**
RC Status **NO**



Insurance & Tax **NA, NA**
HPA Status , HPA Bank **Yes, mmfsl**



Chassis Number **MA3FHEB1S00439807**
Engine Number **D13A2139008**

Damage Reported

Repo

Report Request By
**Mahindra & Mahindra
Financial Services Ltd**

Overall Remarks
NO DAMAGE VEHICLE

Rating	Vehicle Condition	Engine Condition
10 or 9	Excellent	Excellent
8 or 7	Good	Good
6 or 5	Average	Average
4 or 3	Bad	Bad
2 or 1	Scrap	No Engine

Vehicle Summary :
no bratty.setuet bord .remord.bad




Approved by
G. Praveen Kumar
G.Praveen Kumar,
Head e-Business.
www.autoinspekt.com



Use your smart phone to scan the QR code and get detailed autoinspekt report



EXTERIORS



FRONT - BONNET	Average	6/10
BUMPER FRONT	Average	6/10
HEAD LAMPS	Bad	4/10
RH SIDE - FENDER,DOORS	Average	6/10
REAR	Average	6/10
BUMPER REAR - BONNET	Average	6/10
TAIL LAMPS	Bad	4/10
LH SIDE - FENDER , DOORS	Average	6/10
WINDSHIELD & GLASS (ORIGINAL)	Bad	4/10
PAINT (ORIGINAL)	Bad	4/10
NUMBER OF TYRES	4 TYRES	
REMAINING AVERAGE TYRE LIFE	25%	
SUNROOF / MOONROOF	NA	



INTERIORS



STEERING	Average	6/10
DASHBOARD	Average	6/10
INTERIOR TRIMS	Average	6/10
SEATS	5 Seats	
SEATS CONDITION	Average	6/10
SEAT UPHOLSTERY	NA	
ACCESSORIES (AUDIO,COVERS)	Average	6/10

ABS	No	Reverse Parking Assist	No
Airbags	No	Alloy wheels	No
ESP	No	Cruise Control	No



SYSTEMS & FUNCTIONS



BATTERY	Bad
STARTER MOTOR	Bad
ALTERNATOR	Bad
CUBIC CAPACITY (CC)	0 cc

ENGINE	
CONDITION	Bad
TRANSMISSION	
CONDITION	Bad
HVAC	
AC BLOWER	Bad 4/10
COOLING	Bad 4/10
HEATER	Bad 4/10
CHASSIS AND VEHICLE FRAME	Average 6/10
BRAKES	Average 6/10
SUSPENSION	Average 6/10
LPG / CNG Available?	NA
LPG / CNG Endorsed in RC?	NA
ELECTRICAL COMPONENTS	
IGNITION & FUEL SYSTEM	Bad 4/10
HEAD LAMP, TAIL LAMP	Bad
POWER WINDOWS	Bad 4/10
MUSIC SYSTEM	Bad 4/10



VEHICLE CONDITION & DOCUMENT DETAILS



Vehicle Condition	Towed	Parking Location	Yard
Insurance Type	NA	RC Status	NO
Repo Date	15/09/2016		

ESTIMATED ASSESSMENT

BUYER MARGIN	20000	WARRANTY COST	7500	REFURB COST	30000
TRANSPORTATION COST	2500	INSURANCE COST	17000	PARKING CHARGES	68880
RTO EXPENSES	15000	TAXES	0	TOTAL COST	92000



DISCLAIMER

- This report is generated by Autoinspekt - A division of Mahindra First Choice Wheels Ltd (MFCW) at the sole request of the party whom this report is addressed and is to be used solely by the said party for the stated purpose only. Autoinspekt will not be held liable for any loss or liability sustained by any third party relying on the Valuation Report. Autoinspekt has relied on the odometer reading at the time of inspection / valuation and is not responsible for verifying the genuineness thereof.
- As there is no standard price list for pre-owned / used vehicles, the vehicle valuation indicated in the report is our opinion on the market value of the vehicle at the time of our inspection / valuation, based on our standard valuation methodology and procedures. Actual realization may differ from the valuation indicated in the report and Autoinspekt (including its directors and employees) will not be held liable for any direct, indirect, consequential or exemplary damages for any loss resulting from use of this report. Autoinspekt is not responsible for verifying the genuineness of the title documents of the vehicle and its professional opinion on valuation of the car is primarily based on the condition of the vehicle at the time of inspection / valuation.

PHYSICAL VERIFICATION OF REPOSSESSED VEHICLE

Branch	AMA	Verification date	22/09/2016
Stockyard name	J.P. PARKING YARD	Repossessed since	15/09/2016
Repo Release Date	NA	Stock Current Status	NA

Contract Details

Contract No	2976696	Hirer name	swift
-------------	---------	------------	-------

Vehicle Details

Make	MARUTI SUZUKI	Year of Mfg	2013
Model	SWIFT	Colour	OTHERS
Whether Registered (Yes/No)	Yes	If Yes, Regn No.	TN12B0576
Insurance Status	NA		

Vehicle Condition

Total KM Run	0	Tyre Condition (Good/Average/Bad)	Bad
Whether the vehicle is in Running Condition (Yes/No)	No	Whether the vehicle met with an accident (Yes/No)	Yes
If Yes, the extent of Damage Occured (Total Damage/Partial Damage)	NA		
Condition of the interiors including the seats (Good/Average/Bad)	NA		
Battery, whether Running	No	Vehicle Key	NA
Spare tyre	NA	Air Conditioner	NA
Music System	Yes	Tool box	NA
Others (Please specify)	no bratty.setuet bord .remord		
Expected Market Price of the vehicle as on date of verification (in RS.) - Verification Price	₹ 153400		



Approved by

 G.Praveen Kumar,
 Head e-Business.
 www.autoinspekt.com

Signature of the Verifier

Signature of (BIC /BA)